Machine receiving process. SN. 132

Indicate if machine has chip conveyor then tag the chip conveyor.
Chip conveyor included.

Indicate if the machine has a coolant pump and how many.
Coolant pump included.
2 pumps

List all tooling.
None

List all work holders.
None

List all collets.
None

Give the number of pucks and mark if any are missing.
Total - 7
Missing - 0

Put all tooling, work holders and pucks in a box and mark. ____

List any Sheet metal damage.
None

Make sure all turret plugs are on machine.
Missing - 0

Check voltage of machine and put a pigtail on accordingly. √

Power machine on and state the condition.
Good.

Move all axis. Note any concerns.
None

Run tool changer. Note any concerns.

Good

Run spindles. Note any concerns.

Good

Run parts catcher and conveyor. Note any concerns.

Good

Check all axis backlash readings. Record.

Note any leaking concerns.

None

Note any other concerns.

None

Luke Shaver
Signature

12/14/2020
Date